

GRADIENT CONVERSION CHART

GRADIENT = X%	GRADIENT = X%	GRADIENT = X%	GRADIENT = X%
1 : 10 = 10.000	1 : 53 = 1.887	1 : 96 = 1.042	1 : 295 = 0.339
1 : 11 = 9.091	1 : 54 = 1.852	1 : 97 = 1.031	1 : 300 = 0.333
1 : 12 = 8.333	1 : 55 = 1.818	1 : 98 = 1.020	1 : 310 = 0.323
1 : 13 = 7.692	1 : 56 = 1.786	1 : 99 = 1.010	1 : 320 = 0.313
1 : 14 = 7.143	1 : 57 = 1.755	1 : 100 = 1.000	1 : 330 = 0.303
1 : 15 = 6.667	1 : 58 = 1.724	1 : 105 = 0.952	1 : 340 = 0.294
1 : 16 = 6.286	1 : 59 = 1.695	1 : 110 = 0.909	1 : 350 = 0.286
1 : 17 = 5.882	1 : 60 = 1.667	1 : 115 = 0.870	1 : 360 = 0.278
1 : 18 = 5.556	1 : 61 = 1.639	1 : 120 = 0.833	1 : 370 = 0.270
1 : 19 = 5.263	1 : 62 = 1.613	1 : 125 = 0.600	1 : 380 = 0.263
1 : 20 = 5.000	1 : 63 = 1.587	1 : 130 = 0.769	1 : 390 = 0.256
1 : 21 = 4.762	1 : 64 = 1.563	1 : 135 = 0.741	1 : 400 = 0.250
1 : 22 = 4.545	1 : 65 = 1.539	1 : 140 = 0.714	1 : 410 = 0.244
1 : 23 = 4.348	1 : 66 = 1.515	1 : 145 = 0.690	1 : 420 = 0.238
1 : 24 = 4.167	1 : 67 = 1.493	1 : 150 = 0.667	1 : 430 = 0.233
1 : 25 = 4.000	1 : 68 = 1.471	1 : 155 = 0.645	1 : 440 = 0.227
1 : 26 = 3.846	1 : 69 = 1.449	1 : 160 = 0.625	1 : 450 = 0.222
1 : 27 = 3.704	1 : 70 = 1.429	1 : 165 = 0.606	1 : 460 = 0.217
1 : 28 = 3.572	1 : 71 = 1.408	1 : 170 = 0.588	1 : 470 = 0.213
1 : 29 = 3.448	1 : 72 = 1.389	1 : 175 = 0.571	1 : 480 = 0.208
1 : 30 = 3.333	1 : 73 = 1.370	1 : 180 = 0.556	1 : 490 = 0.204
1 : 31 = 3.226	1 : 74 = 1.351	1 : 185 = 0.541	1 : 500 = 0.200
1 : 32 = 3.125	1 : 75 = 1.333	1 : 190 = 0.526	1 : 525 = 0.190
1 : 33 = 3.030	1 : 76 = 1.316	1 : 195 = 0.513	1 : 550 = 0.182
1 : 34 = 2.941	1 : 77 = 1.299	1 : 200 = 0.500	1 : 575 = 0.174
1 : 35 = 2.847	1 : 78 = 1.282	1 : 205 = 0.488	1 : 600 = 0.167
1 : 36 = 2.778	1 : 79 = 1.266	1 : 210 = 0.476	1 : 625 = 0.160
1 : 37 = 2.703	1 : 80 = 1.250	1 : 215 = 0.465	1 : 650 = 0.154
1 : 38 = 2.632	1 : 81 = 1.235	1 : 220 = 0.455	1 : 675 = 0.148
1 : 39 = 2.564	1 : 82 = 1.219	1 : 225 = 0.444	1 : 700 = 0.143
1 : 40 = 2.500	1 : 83 = 1.205	1 : 230 = 0.435	1 : 725 = 0.138
1 : 41 = 2.438	1 : 84 = 1.190	1 : 235 = 0.426	1 : 750 = 0.133
1 : 42 = 2.381	1 : 85 = 1.176	1 : 240 = 0.417	1 : 775 = 0.129
1 : 43 = 2.325	1 : 86 = 1.163	1 : 245 = 0.408	1 : 800 = 0.125
1 : 44 = 2.273	1 : 87 = 1.149	1 : 250 = 0.400	1 : 825 = 0.121
1 : 45 = 2.222	1 : 88 = 1.136	1 : 255 = 0.392	1 : 850 = 0.118
1 : 46 = 2.174	1 : 89 = 1.124	1 : 260 = 0.385	1 : 875 = 0.114
1 : 47 = 2.128	1 : 90 = 1.111	1 : 265 = 0.377	1 : 900 = 0.111
1 : 48 = 2.083	1 : 91 = 1.099	1 : 270 = 0.370	1 : 925 = 0.106
1 : 49 = 2.041	1 : 92 = 1.087	1 : 275 = 0.364	1 : 950 = 0.105
1 : 50 = 2.000	1 : 93 = 1.075	1 : 280 = 0.357	1 : 975 = 0.103
1 : 51 = 1.961	1 : 94 = 1.064	1 : 285 = 0.351	1 : 1000 = 0.100
1 : 52 = 1.923	1 : 95 = 1.053	1 : 290 = 0.345	1 : 1050 = 0.095

